

SX - HX

24 VAC FUSED HARNESS ADAPTERS

SERVICE NUMBERS: 112447.0001 &.0002 & 112449.0001 KIT

Tools Required: 5/16 Nutdriver or Screwdriver


Approximate Time: 5 Minutes

⚠ WARNING


BE SURE ELECTRICAL POWER HAS BEEN DISCONNECTED FROM THE INPUT POWER LINES PRIOR TO REMOVING ELECTRICAL BOX COVER. AN APPROPRIATE LOCKOUT/TAGOUT PROCEDURE IS RECOMMENDED.

1. REMOVE POWER FROM UNIT. USE PROPER LOCKOUT/TAGOUT PROCEDURES (REFERENCE OSHA STANDARD 1910.147)
2. OPEN ELECTRIC BOX COVER WITH SREWDRIVER OR 5/16" NUT DRIVER.
3. INSTALL HARNESS AS SHOWN BELOW DEPENDING ON THE PHASE OF OPERATOR.
4. USE WIRE NUTS PROVIDED TO ATTACH TO END DEVICE.
5. HARNESSES WILL ONLY PLUG INTO RESPECTIVE SOCKETS ONE WAY.

REPLACEMENT FUSE = 1AMP, 250VA, FAST ACTING



SINGLE PHASE



THREE PHASE

FOR HELP, CONTACT TECHNICAL SERVICES AT 1-800-275-6187